



<sup>\*</sup> NOTE: Some 2012-15 KTM 690 Duke were assembled with the threaded end of the engine mount bolt on the right side instead of the left side as originally spec'd. In these cases, the bolt will need to be removed and flipped the opposite direction to install these Frame Sliders.